

Work Order ID 151860

151860

Page 1

Thursday, October 20, 2016 2:28:48 PM

Item ID: D4022-041 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Fuel Transfer Pump Assy
 Start Date: 10/13/2016 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 10/14/2016 Req'd Qty: 1.00 *1* Customer: CLEOG01
 Reference: RMA RA112374

Approvals: Process Plan: MF Date: 16-10-30 Tooling: Date: Run Start *NR1*
 QC: Date: SPC (Y/N): Date: Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4022	C								

100 0.00
 100
 QC Memo 0.00
 Quality Control INSPECT RA112374
 D4022-041 X 1 B122412 *SERIAL # 182544
 RETURN TO VENDOR FOR EVALUATION
 DAS 9 9-89
 16-11-25

110 0.00
 110
 Purchasing Memo 0.00
 Purchasing SEND OUT FOR EVALUATION TO VENDOR
 Issue P/O 34457
 1 NOV 29 2016
 DAS 13 9-89

Monday, January 16, 2017 9:12:53 AM

Page 2

NS1

Stop *NS2*

1

1

Customer: CLEOG01

Required Date: 10/14/2016 **Req'd Qty:** 1.00

Run Start *NR1*

Stop *NR2*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

**Insp.
Stamp**

120

JAN 23 2017

DAS
13
9-69

130

1

Identify as per dwg & Stock Location: 81 242 0.00

140

0.00

Packaging

1x

JAN 19 2017

DAS
26
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____							
Misidentified ☐	Past Due ☐								

Work Order ID 151860***151860***

Page 3

Monday, January 16, 2017 9:12:53 AM

Item ID: D4022-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Fuel Transfer Pump Assy
Start Date: 10/13/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 10/14/2016 Req'd Qty: 1.00 ***1*** Customer: CLEOG01
Reference: RMA RA112374

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150	QC21- Final Inspection - Work Order Release	0.00							
150									
QC	Memo	0.00							
Quality Control									

DAS
21
9-89

JAN 20 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Thursday, October 20, 2016 2:28:48 PM

Page 1

Work Order ID: 151860

151860

Parent Item: D4022-041

D4022-041

Parent Item Name: Fuel Transfer Pump Assy

Start Date: 10/13/2016

Required Date: 10/14/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev A 10.02.02 new issue Prelim EC verified by:DD IPP Rev:B
10.05.17 as per ECN10-562 DD verf:EC IPP REV:C 11.11.22
PER ECN11-665 DD VERF:EC IPP REV:D 12.02.08 replace
AN818-6D for AN815-6D DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4022-041		Manufactured	No				Each	0.0000		1			
D4022-041									**				
Fuel Transfer Pump Assy													

1X122412 MF 10-10-20

Inspection Sheet Complete

RA112374

Customer QA Ref #

0

Part Number	Batch / Serial #	Quantity	Part Complete	Rev/CHG Current	New Paperwork	New Labels	Disposition	Work order #	Work order instructions
D4022-041	B122411	1	☐ Yes	☐ Yes	☐ Yes	☐ Yes	RETURN TO SUPPLIER	151860	Fuel pump is making a abnormal sound. Sends pump D4022-1 B122412 serial #182544 to vendor for evaluation.
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			
0	0	0	☐ Yes	☐ Yes	☐ Yes	☐ Yes			

QC Approval: P.D. _____

Date: 12-Oct-16 _____



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO25076

Purchase Order Date 7/18/2014

PO Print Date 7/18/2014

Page Number 1 of 2

Order From :

VU-AER004

AEROSPARES ACCESSORIES INC
20544 CONCESSION # 9,
RR #2
ALEXANDRIA, ON K0C 1A0
CANADA

Ship To : DART AEROSPACE LTD
1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

Contact Name

Vendor Phone 800 355 2157

Buyer

Chantal Lavoie

Customer POID

Customer Tax # 10127-2607

Ship To Contact

Ship To Phone

Terms Net 30

Ship Via:

FedEx Overnight collect

Currency

USD

Ship Acct:

FOB

Destination-Collect

Line Nbr	Reference Vendor Part Number Line Comments Delivery Comments	Description/ Mfg ID	Req Date/ Taxable Promise Date	CD	Req Qty/ Unit of Measure	PO Unit Price	Extended Price
1	A8150-B1 AS PER DWG D4022 REV. C B122412	Fuel Pump DAS 38 9-89	7/30/2014 Yes 7/30/2014 8/22		8.00 Each	\$875.00	\$7,000.00
Line Total:							\$7,000.00
2	TC 250-100 AS PER DWG D4022 REV. C B122413	Fuel Pump	7/30/2014 Yes 7/30/2014 8/22		6.00 Each	\$36.40	\$218.40
Line Total:							\$218.40

Note:

7/18/2014

AEROSPARES ACCESSORIES INC.

20544 CON #9 ,R.R. #2
ALEXANDRIA, ONT. K0C-1A0
TEL 613-525-0924 FAX 613-525-0925

Invoice

Date 8/7/2014 Invoice # 22944

Invoice To

DART AEROSPACE LTD.
1270 ABERDEEN STREET
HAWKESBURY, ON
K6A-1K7

Ship To

DART AEROSPACE LTD.
1270 ABERDEEN STREET
HAWKESBURY, ON
K6A-1K7

P.O. No.	Terms	Rep	Ship	Via	F.O.B.	Project
25076	Net 30	USD	8/7/2014	FEDEX COL...	ALEXANDRIA	

Item	Description	BATCH #	SERIAL #	Quantity	Price Each	Amount
A8150-B1(25...	A8150-B1 FUEL BOOST PUMP NEW OUTRIGHT SALE	4021	180758/180759	2	875.00	1,750.00
A8150-B1(25...	A8150-B1 FUEL BOOST PUMP NEW OUTRIGHT SALE	4021	182539-182544	6	875.00	5,250.00
TC250-100	CLAMP (2.50 DIA) NEW WELDON	4021	WELDON LOT 41486	6	36.40	218.40
F/C	SHIPPING & HANDLING FEDEX COLLECT	W.B.802349177 879			0.00	0.00

The parts supplied hereon were
acquired directly from the O.E.M.,
or an approved supplier/repair
station which maintains a quality
assurance system providing full
traceability to source of supply

Signature _____

Sales Tax Summary

GST (3) On Sales@13.0%
Total Tax


938.39
938.39

Thank you for your business.

Total

\$8,156.79

GST/HST No. 881274476

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: DR00859	
4. Organization Name and Address: Weldon Pump 640 Golden Oak Parkway, Oakwood Village, Ohio 44146 PAH Approval (PQ2411CE)					5. Work Order/Contact/Invoice Number: 57726 & 58291	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	PUMP-MOTOR ASSEMBLY	A8150-B1	-8-	S/N 180758, 180759, 182539-182544	NEW	
12. Remarks: -EXPORT: THIS ARTICLE MEETS THE SPECIAL REQUIREMENTS & THE BASA OF CANADA. -DRAWING #A8150-B1, TITLE: PUMP-MOTOR ASSEMBLY REV.: I, DATE: 17/JAN/2014.						
13a. Certifies the items identified above were manufactured in conformity to: ☒ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.						
13b. Authorized Signature: 		13c. Approval/Authorization No.: DMIR831215CE				
13d. Name (Typed or Printed): DANIEL RAMSER		13e. Date (dd/mm/yyyy): 04/AUG/2014				
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the engine/propeller/article. Where the user/installer performs works in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

AIRBUS HELICOPTERS UK LIMITED
COMPONENT LABEL
REPAIRABLE

Description Aux Fuel Pump.

Pl. No. D402-041 (A850-B) Ser. No. 182544

Details of Defect NOISY RUNNING AND CAUSING

RADIO INTERFERENCE (use reverse side if req.)

TSN 01c TSO 01c

A/C Removed from: G-LEOG

4114634

1027361

See over for repair info.

Date 31/08/16

Engineer [Signature]
Inspector [Signature]
AIRUK
C090

411 403 22015

Nb Log CARD

914335 WP

REPAIRABLE

Chantal Lavoie

From: ablast@bellnet.ca
Sent: Friday, December 09, 2016 2:37 PM
To: Chantal Lavoie
Subject: Re: FW: info

Hello Chantal, here is what Weldon Pump has advised me regarding this warranty claim pump. Upon receipt and testing pump was found to be set at a lower than normal pressure setting, and flow rate was low. The addition of a couple of shims under the relief valve retainer brought full pressure to where it should be and pump tested serviceable. Upon looking back at original build of this pump, it was noted that 4 shims were used in the relief valve to set proper pressure, when pump received requesting warranty only 2 shims were present ?? Weldon Pump assumes somebody tampered with the original factory setting and removed 2 shims therefore lowering the pressure and flow. This may cause the relief valve to interfere with proper flow and pressure, and as well MAY result in noise ?? The manufacturer was able to restore proper pump settings, but was unable to duplicate reason for return or warranty claim. The manufacturer is presuming somebody tampered with the relief valve setting as released from the factory, therefore no warranty will be given. The manufacturer can return this pump in a repaired certified condition complete with F.A.A. 8130-3 form. The charges we will bill to Dart Aerospace will be \$246.43 U.S.Dollars plus applicable taxes. Please advise via return email if we should proceed with the repair as quoted. Best Regards

-
Ian Preston, Q.A.

Aerospars Accessories Inc.,

Canadian Address	USA address
20544, Con. 9, RR2	1 North Main St.,
Alexandria, Ontario.	Massena, NY.
KOC-1A0	13662

1 -613-525-0924 toll free 800-355-2157

Aerospars Accessories Inc.
www.fuelpumpsupply.com
www.totallyblasted.com
www.aerosparsacc.com

---- Chantal Lavoie <clavoie@dartaero.com> wrote:

=====

Hi Ian,
Please see attached for the tag, also the customer says it's got less than 100 hours.
Thanks
Chantal

-----Original Message-----

From: Marc Bellavance
Sent: Tuesday, November 29, 2016 9:21 AM
To: Patrick Duval <pduval@dartaero.com>

Cc: Chantal Lavoie <clavoie@dartaero.com>
Subject: RE: info

Hi Pat,

Customer says that the pump has less than 100 hours in service.

Marc

-----Original Message-----

From: Patrick Duval
Sent: November-29-16 7:56 AM
To: Marc Bellavance <mbellavance@dartaero.com>
Cc: Chantal Lavoie <clavoie@dartaero.com>
Subject: FW: info

Salut Marc,

Can you follow up on this email with the customer, vendor is asking how many hours was put on the pump before he notice the problem

-----Original Message-----

From: Chantal Lavoie
Sent: Monday, November 28, 2016 10:08 AM
To: Patrick Duval <pduval@dartaero.com>
Subject: FW: info

Hi Pat,
See below would need more info on the pump.
Thanks
Chantal

-----Original Message-----

From: ablast@bellnet.ca [mailto:ablast@bellnet.ca]
Sent: Monday, November 28, 2016 9:25 AM
To: Chantal Lavoie <clavoie@dartaero.com>
Subject: Re: info

Chantal, I will gladly request a warranty evaluation from the manufacturer on your behalf. Standard warranty is 1 year 150 hours whichever occurs first. Please advise hours on unit and install date and return as soon as possible. I will forward right away, Please be advised that your existing pump orders will not be shipping until the New Year as the manufacturer has parts shortages. Best Regards

--

Ian Preston, Q.A.

Aerospars Accessories Inc.,

Canadian Address USA address
20544, Con. 9, RR2 1 North Main St.,

Alexandria, Ontario. Massena, NY.
KOC-1A0 13662

1 -613-525-0924 toll free 800-355-2157

Aerospars Accessories Inc.
www.fuelpumpsupply.com
www.totallyblasted.com
www.aerosparsacc.com

---- Chantal Lavoie <clavoie@dartaero.com> wrote:

=====

Good morning Ian,
We have rec'd a fuel pump serial # 182544, would need to return it for an evaluation see attached for papers.
It make a buzzing sound.

Thanks
Chantal

Chantal Lavoie
Purchasing Coordinator

http://www.dartaerospace.com/media/wysiwyg/download/administrative-paperwork/Procurement_Quality_Clauses_revF_1.pdf

DART AEROSPACE
T 1 613 632-5200
F 1 613 632-1053
E clavoie@dartaero.com
1 800 556- 4166
www.dartaerospace.com<<http://www.dartaerospace.com/>>

[cid:image002.jpg@01D24957.908D08B0]
[cid:image002.jpg@01CE0ABC.07E9B810]

Please note that we will be closed for the holiday period starting December 24rd, 2016 and will be back January 3th, 2017.

Happy Holidays

[Image result for happy holidays]<<https://www.google.ca/imgres?imgurl=http://kewlgraphics.com/facebook/graphics/Snowman-gift-happy-holidays/Snowman-gift-happy-holidays.jpg&imgrefurl=http://kewlgraphics.com/facebook/graphics/Snowman-gift-happy-holidays/&docid=tuDR08gPZhrIJM&tbnid=2uN-elzRz9fmnM:&vet=1&w=350&h=409&bih=719&biw=1536&ved=0ahUKEwjf7pnEpLrQAhUP3WMKHyt5BLg4yAEQMwggwKC4wLg&iact=mrc&uact=8>>



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
Tel: 613 632 9577
Fax: 613 632 1053

PURCHASE ORDER

Purchase Order ID PO34457

Purchase Order Date 11/29/2016

PO Print Date 12/12/2016

Page Number 1 of 1

Order From :

VU-AER004

AEROSPARES ACCESSORIES INC
20544 CONCESSION # 9,
RR #2
ALEXANDRIA, ON K0C 1A0
CANADA

Ship To : DART AEROSPACE LTD
1270 ABERDEEN
HAWKESBURY, ON K6A 1K7
CANADA

E-MAILED

DEC 12 2016

Contact Name

Vendor Phone 800 355 2157

Ship To Contact

Ship To Phone

Ship Via: FedEx Overnight collect

Ship Acct:

Buyer

Chantal Lavoie

Customer POID

Customer Tax #

10127-2607

Terms

Net 30

Currency

USD

FOB

Destination-Collect

Line Nbr	Reference Vendor Part Number	Description/ Mfg ID	Req Date/ Taxable	CD	Req Qty/ Unit of Measure	PO Unit Price	Extended Price
	Line Comments		Promise Date				
	Delivery Comments						

1	151860	D4022-041 PUMP (A8150-B1)	12/23/2016	✓	1.00	\$246.43	\$246.43
---	--------	---------------------------	------------	---	------	----------	----------

Yes

12/23/2016

EVALUATION REQUIRED ON ITEM A8150-B1

CL 12/10/13

Line Total: \$246.43

PO Total: \$246.43

✓

CL

Note: Terms & Condition of Purchasing(Suppliers) and Procurement Quality Clauses are an integral part of our AS9100 requirements. To learn in detail, please visit www.dartaerospace.com for further explanation.

Change Nbr:

3

Change Date:

12/12/2016

AEROSPARES ACCESSORIES INC.

20544 CON #9 ,R.R. #2
ALEXANDRIA, ONT. K0C-1A0
TEL 613-525-0924 FAX 613-525-0925

Invoice

Date 2017-01-09 Invoice # 231642

Invoice To

DART AEROSPACE LTD.
1270 ABERDEEN STREET
HAWKESBURY, ON
K6A-1K7

Ship To

DART AEROSPACE LTD.
1270 ABERDEEN STREET
HAWKESBURY, ON
K6A-1K7

P.O. No.	Terms	Rep	Ship	Via	F.O.B.	Project
43357	Net 30	USD	2017-01-09	FEDEX COL...	ALEXANDRIA	
Item	Description	BATCH #	SERIAL #	Quantity	Price Each	Amount
FOHA8150-B1	A8150-B1 FUEL BOOST PUMP FACTORY REPAIR CUSTOMER PROPERTY NO WARRANTY PUMP TAMPERED WITH BY END USER	W/O 63719	182544	1	246.43	246.43
F/C	SHIPPING & HANDLING FEDEX COLLECT	w.b.8042014216 49			0.00	0.00

THIS INVOICE IS IN US DOLLARS

~~AS~~
~~38~~
~~93~~

~~SP17-01-10~~
C217/01/13

The parts supplied hereon were
acquired from the O.E.M.,
or an approved supplier/repair
station which maintains a quality
assurance system providing full
traceability to source of supply.

Signature _____

Sales Tax Summary

GST (3) On Sales@13.0% 32.04
Total Tax 32.04

Thank you for your business.

Total

\$278.47

GST/HST No. 881274476

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: RMA# 2144-1	
4. Organization Name and Address: Weldon Pump 640 Golden Oak Parkway, Oakwood Village, Ohio 44146					5. Work Order/Contact/Invoice Number: 63719	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	Pump/Motor Assembly	A8150-B1	1	182544	Repair	
12. Remarks: Pump/motor assembly repaired and tested to spec per Weldon Pump's JC1000 "JC" series manual Rev. E						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12. N/A			14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with title 14, Code of Federal Regulations, part 43 and respect to that work, the items are approved for return to service.			
13b. Authorized Signature: N/A		13c. Approval/Authorization No.: N/A		14b. Authorized Signature: Steve Carpenter		14c. Approval/Certificate No.: 2WPR261B
13d. Name (Typed or Printed): N/A		13e. Date (dd/mm/yyyy): N/A		14d. Name (Typed or Printed): Steve Carpenter		14e. Date (dd/mm/yyyy): 14/DEC/2016
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs works in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						